



Firmware Update (version 8.17) for Certain Pioneer Audio Receivers

3 August 2017

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update (version 8.17) for certain Pioneer Audio Receivers. **This firmware update is only for the following Pioneer receivers sold in Cambodia, Indonesia, Laos, Malaysia, Philippines, Singapore, Sri Lanka, Thailand and Vietnam:**

DEH-X1950UB	DEH-X4950BT
DEH-X1952UB	MVH-X195UI
DEH-X1953UB	MVH-X395BT
DEH-X2950UI	DXT-X196UB
DEH-X3950BT	DXT-X1969UB

Warning: Installation on any other product could cause irreversible damage.

This firmware update (version 8.17) Corrects error when connecting certain smartphones running Android 6.0 OS to the Pioneer receiver. In order to perform this update, the following items are needed:

- A Pioneer receiver model listed above
- Blank USB storage device (no files), 2 GB or larger in capacity, formatted to FAT32

Steps to install the firmware are provided on the firmware download page. Installation of the update should take no more than ten minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<http://www.pioneer.com.sg/sg/support/firmware/index.html/>
2. Transfer the files to the SD memory card or USB storage device for insertion into the Pioneer Multimedia Receiver.

Questions

If you have any questions, please contact the nearest Pioneer Customer Service at your country. You can refer to www.pioneer.com.sg/sg/support/service/index.html for more information.

Sincerely,

Pioneer Electronics AsiaCentre Pte Ltd