



Firmware Update for Certain Pioneer In-Dash AV Receivers

August 22, 2025

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only the following Pioneer In-Dash AV Receivers sold in the Middle East and Africa**. Installation on any other product could cause irreversible damage.

DMH-AP6650BT

This firmware update corrects the following matter.

- Improved connectivity with smartphones in Android Auto function.
- Minor bug fix.

To perform this update, the following items are needed:

- Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 2 GB or larger in capacity, **must be formatted to FAT32**.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about two minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://pioneer-mea.com/en/software-and-firmware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact your nearest Pioneer Service Centre in your country:

<https://pioneer-mea.com/en/service-centres/>

Sincerely,

Pioneer Gulf FZE